
Pan Faces.



While is this not a guarantee of what will stay in, it comes from some math and a lot of years of experience of what works.

The expansion and contraction of plastics is roughly 1/16" pr ft from 0 to 100 degree's Fahrenheit